


GPS Boundary Data for Schindler-Schmidt



1.			Not found, on Sugar Hill Road
2.	41° 54.185'	72° 22.132'	Iron pin in center of painted set of 4 rock
3.	41° 54.190'	72° 22.077'	Iron pin in center of painted set of 4 rocks, needs taller pipe
4.	41° 54.201'	72° 21.945'	Follow scenic rock trail to avoid swamp/bog, go long way past scenic rock, iron pin in midst of Mountain Laurel, 4 rock pile, needs taller pipe
5.	41° 54.272'	72° 21.872'	Rebar at base of large rock, in the trail, next to flat rock
6.	41° 54.330'	72° 21.801'	Iron pin in boulders, west side of brook
7.	41° 54.372'	72° 21.817'	Iron pin in 4 stone circle
8.	41° 54.441'	72° 21.835'	Iron pin in 3 stone pile, base of small tree
9.	41° 54.449'	72° 21.837'	Iron pin in 3 stone pile, base of large tree
10.	41° 54.463'	72° 21.834'	Iron pin in 3 small stones & 1 large flat rock
11.	41° 54.493'	72° 21.842'	Iron pin in 3 rocks, 20 feet west of tree with barbed wire
12.	41° 54.530'	72° 21.848'	Iron pin in 4 rocks
13.	41° 54.562'	72° 21.859'	Iron pin in 3 rocks
14.	41° 54.591'	72° 21.852'	Iron pin in 3 rocks with wood stake, north of brook
15.	41° 54.631'	72° 21.866'	Iron pin at top of boulder face, 1 rock by it
16.	41° 54.657'	72° 21.984'	Iron pin in 3 rocks
17.	41° 54.662'	72° 21.997'	Iron pin in 3 rocks, near base of tree
18.	41° 54.670'	72° 22.035'	Iron pin on trail, in 4 rocks
19.	41° 54.688'	72° 22.056'	Iron pin in 3 rocks
20.	41° 54.701'	72° 22.081'	Iron pin in 3 rocks
21.	41° 54.719'	72° 22.098'	Iron pin in 2 rocks, at base of tree
22.	41° 54.737'	72° 22.118'	Iron pin in 3 rocks, just east of trail
23.	41° 54.789'	72° 22.050'	Iron pin in 3 rocks, near downed tree
24.	41° 54.838'	72° 21.976'	Iron pin near 1 rock, near Mountain Laurel
25.	41° 54.889'	72° 21.909'	Iron pin 25 feet off road from big tree on road, 20 feet west of culvert, on Kendall Mountain Road
26.	41° 54.890'	72° 21.936'	Pin found 1 foot in from Kendall Mountain Road
27.	41° 54.852'	72° 21.987'	Rebar, no rocks
28.	41° 54.821'	72° 22.032'	Iron pin in 3 rocks
29.	41° 54.791'	72° 22.072'	iron pipe found at correct distance in 2 rocks, did not find nearby rebar
30.	41° 54.761'	72° 22.122'	Rebar and iron pipe in 4 rocks
31.	41° 54.714'	72° 22.187'	Iron pipe near a tree stump
32.	41° 54.699'	72° 22.201'	Drill hole in 6 inch square concrete monument, line continues thru back of chicken coop
32a.	41° 54.652'	72° 22.207'	Found tail pipe, at lot corner, visually right behind house #470
33.	41° 54.628'	72° 22.207'	Not found, property owner agreed lot corner is at east end of stone wall, lines up with barbed wire found on several trees
34.	41° 54.617'	72° 22.194'	Iron pin found at base of tree with barbed wire
35.	41° 54.573'	72° 22.196'	Drill hole not found, but found barbed wire just west of rock outcrop
36.	41° 54.542'	72° 22.215'	Iron pin found
37.	41° 54.521'	72° 22.222'	Iron pin found
38.	41° 54.477'	72° 22.259'	Iron pin at ground level right at back of blue shed, near rocks, needs taller pipe
39.			Not found , probably behind forsythia shrub near the rocks, on Sugar Hill Road
40.	41° 54.485'	72° 22.289'	Iron pipe in clearing with wood stake, on Sugar Hill Road
41a.	41° 54.456'	72° 22.234'	Did not add yellow tape
41.	41° 54.453'	72° 22.229'	Did not add yellow tape, 50 feet inside back line, on side line
42a.			Not found, should be 50 feet inside back line
42.			Not found
43a.	41° 54.423'	72° 22.245'	Drill hole found, 50 feet inside back & side line
43.	41° 54.418'	72° 22.232'	Rebar found
44a.	41° 54.399'	72° 22.293'	Iron pipe found, 50 feet inside side line, on Sugar Hill Road
44.			Not found, probably in from 2 nd wood post, on Sugar Hill Road