

| 1 | N 41° 53.216′ | W 72° 21.433′ | Entrance right side – no pin since not a bend |
|----|---------------|---------------|---|
| 2 | N 41° 53.217′ | W 72° 21.342′ | Back corner of Susan Drive property owner |
| 3 | N 41° 53.177′ | W 72° 21.335′ | |
| 4 | N 41° 53.126′ | W 72° 21.332′ | |
| 5 | N 41° 53.073′ | W 72° 21.342′ | |
| 6 | N 41° 53.072′ | W 72° 21.326′ | |
| 7 | N 41° 53.069′ | W 72° 21.292′ | |
| 8 | N 41° 53.049′ | W 72° 21.260′ | |
| 9 | N 41° 53.039′ | W 72° 21.193′ | |
| 10 | N 41° 53.031′ | W 72° 21.142′ | Could be #11 |
| 11 | | | Pin not found along stone wall |
| 12 | N 41° 53.037′ | W 72° 21.114′ | Follow stone wall to creek |
| 13 | N 41° 53.096′ | W 72° 21.164′ | Tree, no pin found |
| 14 | | | No pin found, found a lot of barbed wire |
| 15 | N 41° 53.213′ | W 72° 21.188′ | Cross creek |
| 16 | N 41° 53.226′ | W 72° 21.067′ | Along road |
| 17 | N 41° 53.574′ | W 72° 21.052′ | Along road just north of rise |
| 18 | N 41° 53.582′ | W 72° 21.083′ | |
| 19 | N 41° 53.593′ | W 72° 21.130′ | |
| 20 | | | No pin found, found barbed wire |
| 21 | N 41° 53.624′ | W 72° 21.258′ | Along road |
| 22 | N 41° 53.600′ | W 72° 21.274′ | Along road |
| 23 | N 41° 53.580′ | W 72° 21.232′ | Behind woodpile |
| 24 | N 41° 53.535′ | W 72° 21.167′ | |
| 25 | N 41° 53.503′ | W 72° 21.202′ | |
| 26 | N 41° 53.480′ | W 72° 21.241′ | |
| 27 | N 41° 53.543′ | W 72° 21.346′ | Along road |
| 28 | N 41° 53.500′ | W 72° 21.400′ | Down from metal guard rail on road |
| 29 | N 41° 53.486′ | W 72° 21.358′ | |
| 30 | N 41° 53.396′ | W 72° 21.353′ | |
| 31 | N 41° 53.294′ | W 72° 21.341′ | No pin, rebar in ground |
| 32 | N 41° 53.278′ | W 72° 21.341′ | Large tree |
| 33 | N 41° 53.277′ | W 72° 21.391′ | |
| 34 | N 41° 53.271′ | W 72° 21.484′ | |
| 35 | N 41° 53.260′ | W 72° 21.506′ | |
| 36 | N 41° 53.209′ | W 72° 21.504′ | Back corner of Susan Drive property owner |
| 37 | | | Pin not found |
| 38 | | | Entrance left side, pin not found |